

Inspection Report

Permit Number:

Inspection Type:

Inspection Date:

Start Date/Time:

End Date/Time:

Last Inspection:

Weather: Sunny, 90's

InspectionID Report Number: 2073

C0070006

PARTIAL

Tuesday, July 21, 2009

7/21/2009 10:00:00 AM

7/21/2009 2:00:00 PM

Tuesday, June 16, 2009

Accepted by: jhelfric

8/4/2009

Inspector: Steve Demczak, Environmental Scientist III



State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

Company

OGM

Permitee: PLATEAU MINING CORP
Operator: PLATEAU MINING CORP

JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT

Lieutenant Governor

Site: STAR POINT MINE

Representatives Present During the Inspection:

Dennis Ware Controller

Steve Demczak Environmental Scientist III

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	8,919.91
Total Disturbed	113.34
Phase I	
Phase II	
Phase III	

Mineral Ownership

✓ Federal
✓ State

☐ County
✓ Fee

Other

Types of Operations

✓ Underground☐ Surface☐ Loadout☐ Processing☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

Inspector's Signature:

Stophen Jougal

Date

Monday, July 27, 2009

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Tuesday, July 21, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		\checkmark	
2.	Signs and Markers	✓		~	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	V		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		V	
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations		✓		
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		V		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓		~	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		~	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		✓	
13.	Revegetation	✓		~	
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.l	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Tuesday, July 21, 2009

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

No new permitting actions has taken place since the last inspection. The permittee has received Phase II bond release at Starpoint Mine from the Division.

2. Signs and Markers

The identification signs is next to the road to the site.

3. Topsoil

All topsoil was used for reclamation.

4.a Hydrologic Balance: Diversions

The diversions were functioning as designed.

4.c Hydrologic Balance: Other Sediment Control Measures

The complete site is pocked to prevent sediment from leaving the reclaim area.

4.d Hydrologic Balance: Water Monitoring

I went with the permittee in take water monitoring samples at the Star Point Mine for the the third quarter of 2009. All site were dry.

8. Noncoal Waste

The site was clear of non-coal waste materials.

10. Slides and Other Damage

No slides or other damage were noticed during the inspection.

12. Backfilling And Grading

The disturb area is completely backfilled and graded. The permittee received Phase II bond release from the Division.

13. Revegetation

The area was seeded and vegetation is growing.

18. Support Facilities, Utility Installations

There are no facilities at this site